

Top 10 ADA Violations in California

Share This Story, Choose Your Platform!

Based on information from lawsuits filed against The Americans with Disabilities Act (ADA) violations, as required by California Senate Bill 1186, the California Commission on Disability Access (CCDA) has compiled the following list:

Top Ten Alleged Construction Issues (Jul-Dec 2019)

Rank	Description	%
1	Access Height of Goods, Support, Services, and Equipment: Heights of surfaces such as counters, bars, or tables are not compliant.	21
2	Exterior Path of Travel - Pathway: Routes to and from parking lot or public right of way are not accessible . May include uneven surfaces or lack of detectable warnings.	11
3	Number of Handicap Parking Spaces: Parking lot does not contain a minimum number of accessible parking spaces.	9
4	Parking Spaces: Existing parking spaces are not compliant; fading blue paint or excessive slope.	9
5	Interior Path of Travel: Path of travel features not accessible including non-compliant surfaces, excessive slope, cross-slope, etc.	5
6	Exterior Path of Travel - Door Hardware: Thresholds, handles, pulls, latches, locks, or other operating devices are not accessible. Lacking door kick plates.	5
7	Parking Signage: Signage in parking lot is not compliant (e.g. spaces need to be designated as reserved by a sign showing the symbol of accessibility).	4

Rank	Description	%
8	Parking Areas: Loading zones and van access aisles are not compliant or non-existent.	4
9	Access to Goods, Support, Services, and Equipment: Accessible lodging units are non-existent, inaccessible, or insufficient in quantities.	3
10	Exterior Path of Travel - Ramps: Curb ramps or entrance ramps are not compliant or non-existent.	3

**edited for ease of reading. Read original table [here](#).*

These ADA violations account for 74% of the total violations. The remaining allegations are less common but still enforceable and actionable.

Penalties and fines for these violations can be costly. Select law firms have targeted businesses for ADA lawsuits in California, as the laws are more favorable to plaintiffs than elsewhere.

Facilities interested in an evaluation or that suspect violations should be inspected by a professional Certified Access Specialist (CAsp), licensed by the state of California in order to provide adequate access to all customers and minimize business liability.

[CAM Property Services](#) has [supported](#) property managers and facilities in California since 1987. In addition to [building services](#), landscape, hardscape, construction, and maintenance, CAM offers fully integrated ADA compliance and CAsp inspections, [remediation](#), and repair services. Contact CAM today at [800-576-3050](tel:800-576-3050).

Recent Posts


- [Prepare Your Property for the Holidays with CAM Property Services](#)
November 7, 2025
- [How CAM's Client Success Center Makes Property Management Easier](#)
October 20, 2025
- [CAM Property Services at ICSC@Western in Palm Springs - September 28-30](#)
September 24, 2025

- [Minimum Wage Increases Are Here: What They Mean for Your Bottom Line](#) August 21, 2025
- [Celebrating 50 Years of KYCC: Planting Roots for a Greener Future](#) July 21, 2025

Categories

Categories ▼

[Back To All Blog Posts](#)




Stay up-to-date with our property services resources
Subscribe to our free newsletter

SUBSCRIBE NOW

Δ

×



Discover Professional Property Services

All Your Facility Needs From One Source

Benefit from the reliability of professional janitorial services, landscaping, property inspection and facility maintenance combined with the convenience of managing it all through one service provider. Big or small, we can do it all.

[Send Us a Message](#)

[1-800-576-3050](#)